



TOYOTA

Toyota Motor Sales, U.S.A., Inc.
19001 S. WESTERN AVE.
P.O. BOX 2991
TORRANCE, CA 90509-2991
(310)618-4000
(310)618-7800 Fax

June 28, 1991

TO: ALL TOYOTA DEALERS, SERVICE AND PARTS MANAGERS

SUBJECT: SPECIAL SERVICE CAMPAIGN - M01

Toyota will initiate a special service campaign to replace the fuel tank with an improved design on certain 1981-1990 Toyota Land Cruisers.

Continuous driving under extremely severe conditions can create high vapor pressure within the fuel tank, and the repeated high pressure may eventually cause a crack to develop in the tank. You are requested, using the following information, to replace the fuel tank with an improved design on the vehicles involved in this campaign, including any vehicles currently in your stock.

Note: You will be sent SSC notifications with your dealer's name and address for vehicles which, according to our record, you have in stock. If any vehicles in your stock involved in this campaign have been sold to an ultimate customer prior to receipt of this notification, please contact this known customer and perform the necessary repairs.

1. Owner Notification Letter Mailing Date

Phase 1, July 12, 1991 (copy attached)

2. Identification of Involved Vehicles:

Model	Model Year	VIN		Production Period
		VDS	VIS	
Toyota	1981-1987	FJ60G FJ60V	0000691-1140113	9/80-08/87
Land Cruiser	1988-1990	FJ62G	0073630-1121649 0800007-0800211	8/87-12/89

Note: Although the involved vehicles are within the above VIN ranges, not all vehicles in these ranges were imported into the U.S.